

Government Gazette

WESTERN AUSTRALIA

(Published by Authority at 4.30 p.m.)

(REGISTERED AT THE GENERAL POST OFFICE, PERTH. FOR TRANSMISSION BY POST AS A NEWSPAPER.)

No. 50.]

PERTH: THURSDAY, 3rd JULY

[1958.

Crown Law Department, Perth, 30th June, 1958.

THE undermentioned regulations made by the Governor under the provisions of the Factories and Shops Act, 1920-1957, and published in the Government Gazette on the 15th October, 1957, are reprinted pursuant to the Reprinting of Regulations Act, 1954, by authority of the Minister for Justice.

R. C. GREEN, Under Secretary for Law.

Reprinted pursuant to the Reprinting of Regulations Act, 1954, by authority of the Minister dated 24th June, 1958.

WELDING AND CUTTING REGULATIONS, 1957.

Part I.-Preliminary.

- 1. These regulations may be cited as the Welding and Cutting Regulations, 1957, and shall apply to factories or parts of factories where gas welding and cutting, electric arc welding and cutting and resistance welding are carried on, but shall not affect any process or operation being carried on in those factories or parts of factories to which process or operation the Electric Accumulator Regulations, 1931, or the Factories (Poisonous Substances) Regulations, 1932, apply lations, 1932, apply.
 - 2. In these regulations subject to the context-

 - "confined space" means a boiler, tank, vessel, drum, barrel, receiver or other similar enclosed space;
 "distant breathing air mask" means an arrangement of face mask equipped with the necessary valves and fitted with a hose connected in such a way and of such a length that the distal end of the hose is placed in fresh air;
 - "positive pressure air mask" means an arrangement of face mask or hood and a hose connected to the face mask or hood through which fresh air is supplied to the wearer by a compressed air cylinder or compressor;
 - "welder" means any person engaged in gas welding or cutting, electric arc welding or cutting, or resistance welding.