

106. No other vessel to be alongside

- (1) The Master of an explosives vessel must not permit his or her vessel to go alongside any Berth for the purpose of unloading explosives, if any other vessel (whether or not it is an explosives vessel) is alongside at the same time.
- (2) The Master of a vessel (whether or not it is an explosives vessel) must not permit his or her vessel to go along side any Berth whilst unloading is in progress from an explosives vessel.
- (3) A person must not carry out work of any kind on the wharf whilst the unloading of an explosives vessel is in progress unless such work is directly necessary for the unloading of explosives from the vessel.
- (4) Any Master who contravenes sub-bylaw (1) or (2), or any person who contravenes sub-bylaw (3) commits an offence.